

10003347-103004




Figure 1. A section of plasterboard was treated with a Mildew Shield. The presence of coating is visible under a black light.




Figure 2. The coating of a grout and tile protector is visible under a black light.




Figure 3. After three coats of floor finish on the vinyl tile, a strip of floor in high traffic area was coated with a floor finish containing fluorescence dye.

A dark, grainy, black and white photograph of a textured surface, possibly a book cover or endpaper. The image shows a dense pattern of small, light-colored specks and fibers against a dark background, creating a mottled and aged appearance. The texture is uneven, with some areas appearing slightly brighter than others, suggesting a rough or fibrous material. The overall effect is one of antiquity and wear.

Figure 4. 3M Scotchgard coated on a piece of carpet. The distribution of the carpet protector is visible under a black light.